




N02-P1 Inputs Drawing

File Name: N02-P1 Drawing

Last Changed: 27/01/2015



- | | | |
|-----|--------|---------------------|
| 1. | Red | Down Shift Button |
| 2. | Blue | TPS Signal 0V to 5V |
| 3. | Yellow | Profile Switch |
| 4. | NC | |
| 5. | Red | Speed Sensor + |
| 6. | Red | PRM Sensor + |
| 7. | Blue | Up Shift Button |
| 8. | Red | Reverse / Shifter |
| 9. | Red | +5V Out |
| 10. | Orange | +12V Supply In |
| 11. | Blue | Speed Sensor |
| 12. | Green | RPM Input |

Connector Pinouts

